



CANADA

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

N. 7940-1-306

File No. 306
Drilling Authority No. 306

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Canoe River East Chance YT C-18

Location: 66°07'08.93"N., 137°17'57.422"W. Status: D & A April 1968

This location was inspected by the undersigned on 9th July 1971

The location is in ~~satisfactory~~/unsatisfactory condition. T.D. 5035'

The following items require attention:

1. Remove timbers from around cellar and backfill
2. Pile and burn all lumber
3. Bury 5 gal. cans and other junk
4. Paint identifier pipe and plate fluorescent orange.
5. Incorrectly identified - correct
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

Identified as Canoe River East Chance YT D-18

1" instead of minimum 2" pipe used

Inspected by *M. D. Thomas*

M. D. Thomas
District 2









