



File No. .... 156 .....  
Drilling Authority No. ....

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Socony Mobil - WM Birch YT B-34

Location: 66.05087° N., 136.85486° W. Status: Suspended Gas 1965

This location was inspected by the undersigned on 9th July 1971

T.D. 5413'

The location is in ~~satisfactory~~/unsatisfactory condition.

The following items require attention:

- 1. Pile and burn all lumber
- 2. Bury steel drums and other junk
- 3. Remover storage tanks.
- 4. \_\_\_\_\_
- 5. \_\_\_\_\_
- 6. \_\_\_\_\_

Other comments and recommendations: (Include Map, if necessary for clarity)

Identified as Birch #1 YT B-34

Valve padlocked

Ground never leveled

Inspected by \_\_\_\_\_

M. D. Thomas  
District 2