



File No. ....  
Drilling Authority No. <sup>2</sup>.....  
330

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: INUVIK Date: 10 JUL 71

TO: The Oil Conservation Engineer:

RE: MCD GCO NORTHUP TAYLOR LK YT K-15

Location: 65.91083N 133.05000 Status: D&A 1969

This location was inspected by the undersigned on 10 July 1971

The location is in satisfactory/unsatisfactory condition. TD 7804

The following items require attention:

1. REMOVE PLANKS FROM AROUND CELLAR, CLEAN OUT AND BACKFILL
2. WELD IDENTIFIER PIPE TO CASING OR SET IN CONCRETE BLOCK
3. PAINT IDENTIFIER PIPE & PLATE FLUORESCENT ORANGE
4. PILE AND BURN ALL LUMBER
5. BURY OR REMOVE CEMENT AND CEMENT FONDU
6. BURY ALL PLASTIC SHEETING, STEEL DRUMS AND OTHER DEBRIS

Other comments and recommendations: (Include Map, if necessary for clarity)

SMOKE VERY BAD - VISIBILITY < 1/2 MI. HAD TO GO TO 6500' TO SEE.

NO CLEANUP DONE ON THIS LEASE

~~BLACK POLYETHYLENE, CEMENT, CEMENT FONDU~~

~~2" PIPE NOT WELDED~~

FEW DRUMS SCATTERED AROUND

35 MAP (23) (24) (25) (26)

(21) SMOKE FROM 6000'

~~35~~ FILM NOS : 20, 21, 22, 23, 24  
                  ↑  
                  DUD

Inspected by \_\_\_\_\_



File No. ....  
Drilling Authority No. 330 .....

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 10th July 1971

TO: The Oil Conservation Engineer:

RE: McD GCO Northup Taylor Lk YT K-15

Location: 65.91083°N., 133.05000°W. Status: D & A 1969

This location was inspected by the undersigned on 10th July 1971

The location is in ~~satisfactory~~ unsatisfactory condition. T.D. 7804'

The following items require attention:

1. Remove planks from around cellar, clean out and backfill
2. Weld identifier pipe to casing or set in concrete block
3. Paint identifier pipe and plate fluorescent orange.
4. Pile and burn all lumber
5. Bury or remove cement and cement fondu.
6. Bury all plastic sheeting, steel drums and other debris.

Other comments and recommendations: (Include Map, if necessary for clarity)

Smoke very bad, visibility-- $\frac{1}{2}$  mi. Had to go to 6500' to see.

No clean-up done on this lease

Few drums scattered around.

Inspected by *M. D. Thomas*