



File No.
Drilling Authority No.230.....

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: INUVIK Date: 10th July 1971

TO: The Oil Conservation Engineer:

RE: SHELL PEELE R YT I-21

Location: 66.17681° N., 134.31449° W. Status: DNA March 1966

This location was inspected by the undersigned on 10th July 1971

The location is in satisfactory/unsatisfactory condition. TD 6800'

The following items require attention:

1. Pile and burn all lumber.
2. Bury or remove steel drums, wire rope, plastic sheeting and scrap iron.
3. Provide identifier plate 2'x3' and weld or bolt to existing 2" pipe minimum of
4' above ground level.
4. _____
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)


Right on lake (a large one).

Lease never cleaned up.

5 Steel drums

200' wire rope

Polyethelene Sheet (white)



Inspected by M. D. Thomas