



CANADA

File No.
Drilling Authority No. ... 144

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik, District #2 Date: September 21, 1972

~~XX~~

RE: Socony Mobil Western Minerals Ellen YT C-24 (66-40-137-45)

Location: 66-33-09 — 137-50-08 Status: D & A 3-4-65

This location was inspected by the undersigned on August 24, 1972

The location is in ~~satisfactory~~/unsatisfactory condition.

The following items require attention:

1. The drill cutting pile to be levelled.
2. Piles of junk and scrap metal to be buried.
3. All wood debris and other combustibles may be burned.
4. _____
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

The brush originally piled against edges of site are overgrown enough to not warrant disturbance.

Except for many individual piles of junk and scrap, the lease is in excellent condition. However, there are too many of these piles for the lease to be considered in satisfactory condition.

Inspected by *D. A. Bohun*

D. A. Bohun