



File No.
Drilling Authority No. 203

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: INUVIK Date: 10th July 1971

TO: The Oil Conservation Engineer:

RE: SHELL PEELE R YT K-76 10-30-132-00

Location: 66.42650 N., 134.23552 W. Status: DCA Nov. 1965


This location was inspected by the undersigned on 10th July 1971

The location is in satisfactory/unsatisfactory condition. TD 4550*

The following items require attention:

1. Pile all lumber and burn.
2. Bury all rubbish, steel drums, plastic sheeting, stainless steel mesh, etc.
3. Provide identifier plate 2'x3', bolted or welded to 2" pipe a minimum of 4' above
4. ground level. This pipe may be welded to casing or set in concrete block above
5. casing. Paint identifier pipe and plate fluorescent orange.
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)



Inspected by *L. McDonald*
M. D. Thomas