



DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 10th July 1971

TO: The Oil Conservation Engineer:

RE: Shell Peele R YT B-6 and B-6A

Location: 66.58594° N., 134.76042° W. Status: D & A 1966

This location was inspected by the undersigned on 10th July 1971

The location is in ~~satisfactory~~ unsatisfactory condition. T.D. 1412' (B-6)
T.D. 3500' (B-6A)

The following items require attention:

1. Bury plastic sheeting and scrap iron
2. Provide identifier plate 2' x 3' with correct names. This plate to be a minimum of
3. 4' above G.L.
4. Paint identifier pipes and plates flourescent orange.
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

Lease not bad but non-degradable plastic sheeting not buried. Some steel can be seen.

B-6 identified as Shell YT B6-1
B-6A identified as Shell YT B-2-6

B-6 abandoned in December 1966

B-6A abandoned in January 1967

Inspected by _____

M. D. Thomas
District 2