



CANADA

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 10th July 1971

TO: The Oil Conservation Engineer:

RE: Shell Peele R. YT H-59

Location: 66.64051°N., 134.65931°W. Status: D & A April 1967

This location was inspected by the undersigned on 10th July 1971

T.D. 2504'

The location is ~~insatisfactory~~/unsatisfactory condition.

The following items require attention:

1. Either reweld identifier pipe or set in concrete block
2. Provide identifier plate 2' x 3' and weld or bolt to pipe min. of 4' above G.L.
3. preferably 6' above G.L.
4. Bury non-degradable black polyethylene sheeting.
5. Paint identifier pipe and plate fluorescent orange.
- 6.

Other comments and recommendations: (Include Map, if necessary for clarity)

Identified as H-59, not sufficient.

Pipe broken off at base - ready to fall.

Inspected by: M. D. Thomas
Original to Oil Conservation Engineer, Dept of IA & ND, Duplicate to Field Office or Inspecting Engineer. District 2

N. 7940-1-268

File No.
Drilling Authority No. 266