



File No. 210
Drilling Authority No.

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 10th July 1971

TO: The Oil Conservation Engineer:

RE: Shell Peele R. YT L-1 86-40-134-45

Location: 66.51065°N., 134.77457°W. Status: D & A February 1966

This location was inspected by the undersigned on 10th July 1971


T.D. 6020'

The location is in ~~satisfactory~~ unsatisfactory condition.

The following items require attention:

1. Pile and burn all lumber
2. Bury drums, plastic sheeting and scrap iron.
3. Provide identifier plate 2' x 3' and bolt or weld to existing identifier pipe
4. minimum of 4' above G.L.
5. Paint identifier pipe and plate fluorescent orange.
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)



Inspected by Lu S. Thomas