

DRILLING AND SERVICE RIG INSPECTION REPORT

Date of Inspection Jan. 14, 1973 (14:40) Date of Last Inspection Nil
 Well Name Westcoast et al. N. Porcupine. Y.T. F-72 Location 67° 31' 23" N 137° 59' 06" W
 Operating Company Westcoast Contractor Brinkerhoff Rig No. 19

Operation in Progress Erecting, preparing Depth 60' Projected
 to spud in 2 or 3 days. Total Depth 9500'
 Spud Date Not spudded D.A. No. 625 Conservation
 Depth of last casing string Refrigerated String at 60' Engineer S.F. Blue
 Toolpush H. Cooper Representative Perthume

Signature Signature Signature

N.B.: See Page 2 - Remarks re items checked as 'Unsatisfactory' or 'No'.

I. GENERAL	Yes	No	Remarks
1. D.A. posted	Yes	No	Fireproof material in rig shelter
2. Tour Reports complete, up to date and signed.	Yes	No	20. Wiring high enough above ground for clearance.
3. Location of wellsite with respect to natural & installed facilities	Yes	No	21. Hard hats worn on rig or in potentially dangerous areas.
4. Dump adequately contained	Yes	No	22. All breathing apparatus tested monthly & recorded in tour book.
5. Housekeeping	S	US	III. MUD SYSTEM
6. Radio communication in working order.	Yes	No	1. Mud tank capacity
7. Camp & kitchen facilities clean and sanitary.	Yes	No	2. Safety valve on pump discharge line
8. Adequate waste disposal	Yes	No	Type:
9. Deviation surveys every 500' minimum and recorded in tour book	Yes	No	3. Mud weight relative to depth.
IV. CAMP			4. Gas analyzer.
1. Flare pit and burn pit greater than 150' from wellbore.	Yes	No	5. Degasser, if mud tanks in rig shelter
2. Boilers greater than 150' from the wellbore.	Yes	No	6. Mud level warning system. Type:
3. Rig lights operating and with protective covers.	Yes	No	7. Condition of Kelly hose.
4. Electrical fixtures within 75' of wellbore explosion proof.	Yes	No	8. Mud mixing platform clean.
5. Power plant grounded.	Yes	No	9. Studs and nuts on fluid cylinder head and valve covers.
6. Adequate Gas masks; Type:	Yes	No	10. Pressure rating of mud discharge line
7. Resuscitator with adequate supply of air.	Yes	No	11. Mud gun anchors.
8. Minimum of two 20# powder fire extinguishers in doghouse.	Yes	No	IV. ENGINES AND FUEL
9. Minimum of two 5 gal. CO2 fire extinguishers in each boiler house.	Yes	No	1. Condition of motors
10. Fire extinguishers in camp.	Yes	No	2. Engine air inlets greater than 40' from wellbore.
11. First aid kits; No.:	S	US	3. Engine exhausts greater than 40' from wellbore.
12. Safety bottles	S	US	4. Where engine exhausts exceed 400°F., such exhausts less than 75' from wellbore are insulated
13. Stretchers and blankets	Yes	No	5. Motor safety shut down on floor.
14. All moving parts safely guarded	Yes	No	6. Condition of fuel lines.
15. Necessary guard rails in place	Yes	No	7. Shut-offs checked weekly and recorded on tour sheets.
16. Safety meeting held and recorded in tour book.	Yes	No	8. Water connections on engine exhausts working.
17. Fuel storage greater than 75' from wellbore.	Yes	No	V. FLOOR AND DERRICK
18. Every trailer has valid first aid certificate.	Yes	No	1. Stabbing valves handy.
19. Air support for medical emergency	Yes	No	2. Kelly cock operation.
			3. Emergency alarm.
			4. Tong lines and tong dies.
			5. Hoisting line examined weekly and recorded in tour book
			6. Exits from all four sides of rig floor.

* Satisfactory
 ** Unsatisfactory