



Field Report 107071014

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

PHONE (403) 633-3070
TELEX 036-8496

Started... Sept. 27... 1993

Completed... Oct. 3... 1993

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Public Works Canada 24 Range Road L.M. Zaccarelli	W/W 93-17-17	Health center Destruction Bay Dewatering wells

FORMATION LOG			DESCRIPTION OF WORK	TIME			
DATE	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Loading	Sept 27	8:00	12:00	4
			Travel	"	1:00	5:00	4
			remove fence	"	5:00	5:30	0.5
			move on set up	"	5:30	7:30	2
			Disconnect pump ready to pull				
			Pull pump	Sept 28	8:00	8:30	0.5
			Pull casing Redrill	"	8:30	7:30	11
			to 60' Trouble. Plugging + closing bit				
			Redrill to 83'	Sept 29	8:00	9:00	1
3	89	Gr.	sand silt	"	9:00	7:00	10
	154	till					
4	161	silt	Gr. sand				
1	177	clay					
7	198	silt	clay Gr.				
8	226	till	with silt clay & Gr layers				

Log of Casing & Pipe				Remarks:
Depth	Type	Size	Type	
ft	Inch	Feet	Inch	
Static Level			Total Rig Time	hrs.
Ground Level			Total Standby	hrs.
Top Of Casing			Drilling Mud	sacks

SIGNATURES

NIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....