	PRO	JECT	T: Fa	aro	Hydrogeological Service	es	CLIENT	T: Yukon Gove	rnment Comr	nuni	ty Se	ervices TE	STHOLE NO:	: Well 5		
	LOCATION: Faro, Yukon						•	-					PROJECT NO.: 5160311			
	CON	TRA	СТО	R:	Midnight Sun Drilling	METHOD: Air Rotary						ELI	EVATION (m)	): 645.871		
	SAMF	LE ]	ГҮРЕ		GRAB	SHELBY	TUBE	SPLIT SPO	ON B	ULK		✓NO	RECOVERY	CORE		
Ī	BACK	BACKFILL TYPE BENTONITE GRAVE				GRAVEL		G	GROUT			CUTTINGS				
	DEPTH (m)		SOIL SYMBOL			SOIL DES	CRIPT	ΓΙΟΝ		SAMPLE TYPE	SAMPLE #	со	MMENTS		APPROX. ELEV. (m)	
ARO BOREHOLE LOGS_CL-5160311.GPJ AECOM_BBY.GDT 07/10/16	-0 -1 -2 -3 -4				Olive brown SILT with trace s	and and gravel cla	asts, dry.				2	steel casing to 2 ground.	eted with a 12 in 23.98 feet (7.31 i	m) below	644 - 6	
	-5 -6 -7 -8 <u>▼</u>				Olive grey SAND with gravel, Grey medium SAND with trac		oist.				4				640	
			000000000000000000000000000000000000000		Grey coarse GRAVEL with sa	and, wet.					7				638	
	-10 -10 11 11			0.0.0.0.0.0.0.0	Black SILT, wet.						9 10 11	Well Screen De 8 feet (2.4 m) lo Veriperm well so	I in SILT on July tails: ing stainless stee creen with rubbe lot (2.54 mm) op	el, wire-round er k-packer.	636 -	
¥	14		m		Marriage Harabii-1-1	td			LOGGED BY:	Jon	athan	Kerr	COMPLETION	N DEPTH: 36		
VIRO			m-		301 Hawkins Street,	ison Hershfield Ltd. Hawkins Street, Suite 101 Phorse Yukon Y14 1X5			REVIEWED B			ight COMPLETION DATE:		N DATE: 15/07/16		
ΞĹ	MORRISON HERSHFIELD Whitehorse, Yukon Y1A 1X5								PROJECT MANAGER: Jonathan Ke				Page 1 of 1			

