



Field Report (109150022)

PH. 633-3070
P.O. BOX 4391
WHITEHORSE, YUKON

Started... Aug. 19 19. 82

Completed... Aug. 19 19. 82

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
YTG? H. L. O. I. D. R. U. N. T. A. L. I. N. G. S. C. H. O. O. L.	W/W	PELLY
PELLY School		

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE MOVE TO SCHOOL - SETUP	Aug 19	1:30	2:00	
0'	50'	SAND & GRAVEL	Pull out - SET SCREEN	"	2:00	3:30	
			DEVELOPE	"	3:30	4:00	
			Pull out - LOAD - WELD ON CAP	"	4:00	5:30	
			WASH TRUCKS - (Thought we were done)	"	5:30	6:00	
				"	6:00	7:00	5 1/2
DEVELOPED TO APPROX 35 G.P.M.							

Ord. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
Feet	Inch	Feet	Inch	46' - 219 WALL 6" CASING
				1 - 6" DRIVE SHAFT
				1 - 15 SLOT SCREEN
				1 - LEAD PACKER
				1 - 5 3/4 BIT PIN BOTTOM
				1 - 2' RISER PIPE
				Static Level 22'
				Ground Level
				Top Of Casing
				Total Rig Time hrs.
				Total Standby hrs.
				Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN..... *[Signature]*
TITLE..... *Brnd*

CLIENT.....
TITLE.....