Field Report

MIDNIGHT SUN DRILLING CO. LTD. WHITEHORSE Y.T.

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

PHONE (403) 633-3070
TELEX 036-8496

Started. July 28 1994

Completed. July 31 1994

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
	W/W #2	Paddle Wheel
	94-17-16	

FORMATION LOG FROM	TO	FORMATION	DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
			MOVE				
			Load	July 28	9:00	12:00	3
			move on set up	"	12:30	2:30	2
0	26	Gr.	Sand	"	2:30	6:00	3.5
26	58	Gr.	Sand silt cobs				
58	60	Till					
60	126	Till		July 29	8:00	7:00	11
26	141	silt	Clay				
41	166	Till					
66	200	Hard	silt Clay odd cob.				
00	306	Hard	silt Clay odd cob.	July 30	8:00	6:00	10
06	312	runny	silt				
12	313	BR					
			Trip hole, Broke sandline chain	July 31	9:00	12:00	3
13	317	Broke	BR	"	~~12:00~~		
			Develop	"	12:00	4:00	4
			Trip out	"	4:00	5:00	1

rd. of Casing & Pipe Size	Type	Size	Type
6			
Feet	Inch	Feet	Inch
14	6		

Remarks: 60 GPM
1 - drive shoe

Static Level		Total Rig Time	hrs.
Ground Level	35'	Total Standby	hrs.
Top Of Casing		Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

TITLE.....

CLIENT.....

TITLE.....

Blow Printers