



Field Report

204110226.

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

PHONE (403) 633-3070
TELEX 036-8496

Started...Aug...1.....19.94.

Completed...Aug.3.....19.94.

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
	W/A	Paddle wheel
	#3	
	94-1A-16	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			move set up	Aug. 1	8:00	9:00	1
0	21	Gr.	sand cobs	"	9:00	6:00	9
21	68	silt	Gr. sand cobs				
68	116	till					
16	136	hard	silt clay old cob.				
36	161	till					
61	180	Hard	silt clay some Gr				
80	295	Hard	silt clay - some Gr.	Aug 2	8:00	4:00	8
295	300	Runny	silt				
300	304	BR					
304	306	fine	sand some Gr				
			Developer	"	4:00	6:00	2
			Developer	Aug 3	8:00	1:00	5
			move off to shop	"	1:00	3:00	2

ord. of Casing & Pipe

Size	Type	Size	Type
6			
Feet	Inch	Feet	Inch

Remarks: 60 GPM
1 - drive shoe.

303			

Static Level	Total Rig Time	hrs.
Ground Level	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....