



**WELL-SITE INSPECTION
REPORT**

**RAPPORT D'INSPECTION DE
L'EMPLACEMENT DU PUIT**

Drilling authority No.
Permis de forage N° 498

From: Field Office or Area - Bureau régional ou zone

Date

Do: COGLA - Yellowknife, N.W.T.

July 25, 1988

To: The Oil Conservation Engineer:
À: L'ingénieur (Conservation des hydrocarbures):

RE: SOBC WM E. Porcupine YT I-13
Au sujet de:

Location - Emplacement

Statut - État

66° 02' 35"N 137° 46' 58"W

D & A

This location was inspected by the undersigned on
L'emplacement a été inspecté par le soussigné le July 20, 1988

The location is in satisfactory unsatisfactory condition
L'état de l'emplacement est satisfaisant insatisfaisant

The following items require attention - Porter une attention spéciale aux articles suivants:

1.

2.

3.

4.

5.

6.

Other comments and recommendations: (include map, if necessary for clarity) - Autres commentaires et recommandations (ajouter des cartes géographiques au besoin)

Some small pieces of wood and debris on the lease.
Sign is in good condition.
Casing is not cut off.
Approximately 30% vegetation growth on the lease.

Bruce Kutz
Inspected by - Inspecteur









