



N-7940-1-151

File No.

Drilling Authority No. 151

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT

OIL AND MINERAL DIVISION

WELL-SITE INSPECTION REPORT

FROM: Field Office or Area: Inuvik Date: 9th July 1971

TO: The Oil Conservation Engineer:

RE: Socony Mobil - WM West Parkin YT D-51

Location: 66.16903°N., 137.43458°W. Status: D & A April 1965

This location was inspected by the undersigned on 9th July 1971

T.D. 4950'

The location is in ~~unsatisfactory~~ satisfactory condition.

The following items require attention:

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____

Other comments and recommendations: (Include Map, if necessary for clarity)

Lease clean



Inspected by M. D. Thomas

M. D. Thomas
District 2

25