

RIG INSPECTION REPORT

Well: SMALL TRAIL RIVER Y.T. H-37-66-40-13U-45
 W. Drilling Authority No: 778
JAN 18/74 Inspection No: 1
 Inspection: FIRST INSPECTION

Date Spud: Nov 27/73
 Depth: 5822 Projected Total Depth: 13200
 Casing Strings: 1 3/4 Size: O.D. Depth set: 24

Inspector: KILBERMAN Signature: _____
PIKOWSKI Signature: _____
MALCROCK Signature: Malcrock

EQUIPMENT

Instructions Conform to those submitted with D.A. Yes No
 D.P. Stack: Satisfactory Unsatisfactory
 Pressure Source and E.C.P. Controls: KOENEY HOUSES ABOUT
HOUSE. FLOOR CONTROLS None
 Like Shut-off tests witnessed

Specifications Conform to those submitted with D.A. Yes No
 D.P. Stack: Satisfactory Unsatisfactory
 Manifold Good

I T E M S

Drilling Authority,	Categories
Warning signs (if in H ₂ S area) and no smoking signs.	Drill Autho & Rep
of all required information in tour reports.	
Equipment appears to be properly connected	Blowo
Equipment tested daily and tests recorded.	Preve
Equipment adequately pressure tested before drilling out casing shoe.	Equip
Equipment housed, ventilated & heated for winter operations.	
& kill lines adequate and properly tied down.	
Controls and accumulator esecquately and properly located.	
Personnel trained and capable of operating E.C.P. equipment.	
Shut-off controls installed and functional.	Fire
Airlocks properly connected with required safety features.	Hazar
Regulation being observed.	
Electric generators, accumulator & fuel supplies at distance from well and from each other.	
Flare line & sump adequate and at required distance from well.	
Well equipment adequate and maintained.	
Electrical wiring and fittings installed and maintained.	
First aid kits, stretchers and blankets available and maintained.	Perfo
24 hour operation.	Safet
Personnel have valid first aid certificates.	
Apparatus - adequate, accessible and maintained.	
Required personnel safety equipment.	
House keeping and indication of good practice.	Gener
Tests appear to conform with CEC & WCA standards.	
Deviation surveys being run.	
Identification of potential hazardous conditions.	
Contingency plans, equipment and supplies.	
Comments or action required on items listed above and other items listed in Inspection Guide should be listed here)	

ALL GOOD CONDITION. EXCELLENT EQUIPMENT.
FACILITIES GOOD.